# EXECUTIVE SUMMARY

QUIESTO: MARIO DAC COST, EST, NEW : DAC RE.USE PLAN CASTAL PERSIBILITY

### **ASSUMPTIONS:**

- Torrance will continue to operate within the guidelines established by the PCO Strategic Plan and the Torrance Five (5) Year Plan.
- Total Torrance population will be between 2,000 and 3,000 employees.
- No major new construction or installation of large equipment (FMS type) or systems.
- All values are based in "1991" dollars.
- Approximately 55 acres will be sold.
- Torrance will continue to operate as a Fabrication Center (no capital dollars identified to change product - convert from fabrication to assembly operations).

The List below is a summary of the capital dollars required by Torrance (C6) through 1998.

	1992	1993	1994	1995	1996	1997	1998	Totals
Description			\$300,000			\$1,260,000	\$100,000	\$7,202,00
nvironmental	\$822,000	\$2,400,000	<del>                                     </del>	\$250,000	\$1,100,000	\$100,000	\$800,000	\$6,275,00
Building	\$900,000	\$1,875,000	\$1,250,000			\$3,350,000	\$2,932,000	\$34,715,00
Equipment	\$4,600,000	\$5,300,000	<del></del>	\$10,313,000	\$4,260,000		\$1,00,000	\$10,260,0
Major Systems	\$810,000	\$1,509,000	\$2,800,000	\$1,500,000	\$1,500,000	\$1,150,000		\$5,845,2
Misc. (10%)	\$713,200	\$1,107,500	\$831,000	\$1,268,300	\$856,000	\$586,000	\$483,200	
Innual Totals:	\$7,845,200	\$12,182,500	\$9,141,000	\$13,951,300	\$9,416,000	\$6,446,000	\$5,315,200	]
5 Year Total:	<del></del>				\$52,536,000			

10% OF TOTAL

Values outlined above include:

Retrofit of approximately forty (40) large N/C machines (\$15,855,000)

0 \$ 1.05M 0 \$ 1.605M

- Removal of all PCB Transformers (\$2,200,000)
- New Drop Bottom Quench Furnace (\$1,500,000)
- New High Pressure Press (\$7,000,000)
- Rearrangement for Improved Production Flow (\$6,000,000)
- Does not include "rebates" from State and Local Agencies for Energy Conservation measures.
- Deferred 1991 Capital Items
- Environmental issues addressed are estimates based on forecasted requirements.

TORRANCE (C6) FACILITY

# MAJOR CAPITAL EXPENSES

		Seven	Year Sumn	nary		,	
Description	1992	1993	1994	1995	1996	1997	1998
Building 1	\$1,275,000	\$2,825,000	\$1,000,000	\$7,300,000	\$1,500,000	\$0	\$0
Building 2	\$765,000	\$1,035,000	\$1,235,000	\$1,148,000	\$680,000	\$1,730,000	\$632,000
Building 3	\$0	\$10,000	\$0	\$0	\$600,000	\$400,000	\$0
Building 29	\$0	\$0	\$0	\$5,000	\$0	\$0	\$0
Building 37	\$1,810,000	\$2,840,000	\$1,775,000	\$1,165,000	\$2,530,000	\$1,520,000	\$1,300,000
Building 61	\$255,000	\$125,000	\$150,000	\$0	\$0	\$0	\$0
Building 66	\$100,000	\$0	\$250,000	\$250,000	\$0	\$0	\$0
Building 67	\$36,000	\$0	\$350,000	\$0	\$0	\$0	\$0
-Common Areas	\$2,891,000	\$4,240,000	\$3,550,000	\$2,815,000	\$3,250,000	\$2,210,000	\$2,900,000
Misc. (10%)	\$713,200	\$1,107,500	\$831,000	\$1,268,300	\$856,000	\$586,000	\$483,200
Annual Totals	\$7,845,200	\$12,182,500	\$9,141,000	\$13,951,300	\$9,416,000	\$6,446,000	\$5,315,200
5 Year Total:				* "	\$52,536,000		
7 Year Total:							\$64,297,200

DESCRIPTION:

**CONSTRUCTION:** 

• Building: Sheet Metal

• Roofing: Sheet Metal/Asphalt and Rock

**BUILDING DATA:** 

Dimensions: 370' x 570'

Truss Height: 25 Feet

Floors: One (1) Floor, Basement, Two (2) Story Office Structure (South-End of Building)

Total SQ. FT.: 313,922Sprinkler System: 100%

**OCCUPANCY:** 

Sheet Metal Fabrication

CONDITION:

Building is in good shape (40 years old) and does not need major repairs for the next 4 to 8 years.

Basement will continue to be utilized as a Tool Storage facility.

Power and compressed air are available in all areas.

• REQUIREMENTS:

Please See Table Below.

		Building	1	,			
Description	1992	1993	1994	1995	1996	1997	1998
Titanium Chem Mill Scrubber Upgrade	\$400,000	\$0	\$0	\$0	\$0	\$0	\$0
Maskant Rm - Structural Bldg. Upgrade	\$0	\$300,000	\$0	\$0	\$0	\$0	\$0
Maskant Rm Emission Ctrl. for Solv. Fumes	\$0	\$500,000	\$0	<b>\$0</b>	\$0	\$0	\$0
New Drop Bottom Quench Furnace	\$500,000	\$1,000,000	\$0	\$0	\$0	\$0	\$0
Verson Press (Fluid Forming Press)	\$6	\$0	\$0	\$7,000,000	\$0	\$0	\$0
Overhaul Industrial Equip. & Process Systems	\$0	\$500,000	\$1,000,000	\$0	\$1,000,000	\$0	\$0
Steam Lines	\$0	\$250,000	\$0	\$0	\$0	\$0	\$0
Water Lines	\$200,000	\$0	\$0	\$0	\$0	\$0	\$0
HVAC	\$0	\$0	\$0	\$0	\$100,000	\$0	\$0
Cranes	\$0	\$200,000	\$0	\$0	\$0	\$0	\$0
Fume and Dust Collectors	\$0	\$0	\$0	\$300,000	\$0	\$0	\$0
Chem Milf (Old) Overhaul	\$75,000	\$75,000	\$0	\$0	\$0	\$0	\$0
Ventilation System Basement Area	\$100,000						
Roof Repair	\$0	\$0	\$0	\$0	\$400,000	\$0	\$0
Annual Totals:	\$1,275,000	\$2,825,000	\$1,000,000	\$7,300,000	\$1,500,000	\$0	\$0
5 Year Total:					13,900,000		
7 Year Tötal:						\$	3,900,000

COMMENTS:

BLOG SHER

\$250K ~200K ~100K

\$ 400K

# 1.05 M

toppe BUBC []

**DESCRIPTION:** 

CONSTRUCTION:

**Building:** 

Sheet Metal

Roofing:

**Double Sheet Metal** 

**BUILDING DATA:** 

Dimensions:

830' x 1130'

Truss Height:

27 Feet

Floors:

One (1) Floor, Multiple Mezzanines, Two (2) Story Office Structure (Patio Offices)

Total SQ. FT.:

915,975

Sprinkler System: 100%

#### OCCUPANCY:

Heat Treat, Process, Welding, Stockrooms, Machine Shops, Tooling, Grinding, Part Storage, Fabrication, Process Labs, Paint, Foundry, Sheet Metal Fabrication

CONDITION:

Building structure is in excellent shape.

Roof was replaced six (6) years ago and should last for at least another ten (10) years.

Steam and water lines need to be repaired/replaced. Power and compressed air are available in all areas. Office areas along the main aisle are soundproof.

Mezzanines have elevators.

**REQUIREMENTS:** 

See Table Below.

		Building:	2	_			
Description	1992	1993	1994	1995	1996	1997	1998
Machine Retrofit/PM	\$90,000	\$120,000	\$0	\$300,000	\$160,000	\$400,000	\$400,000
DNC Upgrade	\$15,000	\$15,000	\$85,000	\$48,000	\$90,000	\$380,000	\$132,000
Maintenance Spares	\$150,000	\$100,000	\$0	\$0	\$0	\$0	\$0
Machine Retrofit/PM (FMS)	\$6	\$0	\$0	\$800,000	\$0	\$0	\$0
DNC Upgrade (FMS)	\$0	\$0	\$0	\$0	\$180,000	\$100,000	\$0
Maintenance Spares (FMS)	\$100,000	\$200,000	\$200,000	\$0	\$0	\$100,000	\$100,000
Modify Upstairs Paint Booth Overflow	\$5,000	\$0	\$0	\$0	\$0	\$0	\$0
Lead Foundry*	\$0	\$0	\$0	\$0	\$0	\$750,000	\$0
Secondary Containment Process Tanks	\$0	\$100,000	\$0	\$0	\$0	\$0	\$0
PCB Transformer Leak Clean-up	\$5,000	\$0	\$0	\$0	\$0	\$0	\$0
	50	\$500,000	\$500,000	\$0	\$0	\$0	\$0
Steam Lines Water Mains (Replacement)	\$400,000	\$0	\$200,000	\$0	\$0	\$0	\$0
Cranes	\$0	\$0	\$Q.	\$0	\$250,000	\$0	\$0
Fume and Dust Collectors	\$0	\$0	\$250,000	\$0	\$0	\$0	\$0
Annual Totals:			\$1,235,000	\$1,148,000	\$680,000	\$1,730,000	\$632,000
5 Year Total:	4.00,000	\$4,863,000					
7 Year Total:							\$7,225,000

**COMMENTS:** 

Dependent upon future SCAQMD Regulations.

TORRANCE (C6) FACILITY

**DESCRIPTION:** 

**CONSTRUCTION:** 

**Building:** 

Triple Brick

Roofing:

Reinforced Concrete

**BUILDING DATA:** 

Dimensions:

34' x 940'

Truss Height:

8 Foot (Floor to Ceiling)

Floors:

Three (3) Floors

Total SQ. FT.:

103,806

Sprinkler System: 100%

#### OCCUPANCY:

Administrative Offices, Credit Union

CONDITION:

Building is in good shape.

Some areas have been refurbished with carpet, Steelcase partitions, drop ceilings and upgraded lighting.

Construction of building is heavy duty.

Credit Union occupies floorspace in the south and of the building and there are plans to relocate off-site

within 1 to 2 years.

**REQUIREMENTS:** 

See Table Below

	/ /	Building 3					
Description	1992	1993	1994	1995	1996	1997	1998
Asbestos Abatement - Ceiling Tiles	\$0	\$0	\$0	\$0	\$300,000	\$200,000	\$0
	\$0	\$0	\$0	\$0	\$300,000	\$200,000	\$0
Asbestos Abatement - Floor Tiles	\$0	<del> </del>	\$0	\$0	\$0	\$0	\$0
Blueprint Room Ventilation	\$0 \$0	\$5,000	\$0	\$0	\$0	\$0	\$0
Restroom Ventilation Repair and Upgrade Amnual Totals:	\$0	\$10,000	\$0	\$0	\$600,000	\$400,000	\$0
S Year Total:		4.0,000			\$610,000		
7 Year Total:							\$1,010,000

**COMMENTS:** 

**DESCRIPTION:** 

**CONSTRUCTION:** 

**Building:** 

Sheet Metal

Roofing:

Gravel

**BUILDING DATA:** 

Dimensions:

180' x 1160'

Truss Height:

30 Feet

Floors:

One (1) Floor

Total SQ. FT.:

210,141

Sprinkler System: 100%

#### **OCCUPANCY:**

Material Storage

CONDITION:

Building strucutre is in fair shape (for use as a warehouse).

Existing structure will not support large overhead cranes (Stacker Crane).

New Low Pressure Sodium lights - recently installed.

Large steel roll-up doors and loading docks at both ends of the building.

Intended for warehouse use only.

Power is available for lighting and cranes only.

Power is not available as a general rule.

Compressed air is not available.

**REQUIREMENTS:** 

See Table Below.

			Building 6	6				
	Description	1992	<del>-19</del> 93	1994	1995	1996	1997	1998
Heaters		\$100,000	\$0	\$0	\$0	\$0	\$0	\$0
Crane (Smai	II - Light Duty)	\$0	\$0	\$0	\$250,000	\$0	\$0	\$0
Paint		\$0	\$0	\$250,000	\$0	\$0	\$0	\$0
	Annual Totals:	\$100,000	\$0	\$250,000	\$250,000	\$0	\$0	\$0
	5 Year Total:					\$600,000		
	ZYear-Total:							\$600,000

**COMMENTS:** 

Not intended for Fabrication use. Power is very limited and compressed air is not available. Building is only to be used as a warehouse facility in its existing condition.

## C6 - Common Areas

DESCRIPTION:

The following items are requirements for common areas within the plant and/or for the smaller buildings located throughout the Torrance (C6) Facility.

REQUIREMENTS:

See Table Below.

	C6 - Comi	non Areas	s - Plant-W	'ide			
Description	1992	1993	1994	1995	1996	1997	1998
Remove Underground Storage Tanks*	\$300,000	\$150,000	\$100,000	\$0	\$0	\$0	\$0
Bldg. 36 - Groundwater & Soil Clean-Up	\$200,000	\$470,000	\$0	\$0	\$0	\$0	\$0
DMJM (Chrome Destruct System)	\$0	\$0	\$0	\$500,000	\$0	\$0	\$0
Monitor Process Tank Chemistry	\$0	\$20,000	\$0	\$0	\$0	\$0	\$0
torm Drain Outfall	\$3,000	\$0	\$0	\$5,000	\$0	\$0	\$0
mergency Lighting - Plant-Wide	\$210,000	\$200,000	\$200,000	\$0	\$0	\$0	\$0
CB Transformer Replacement - Plant-Wide	\$200,000	\$800,000	\$500,000	\$700,000	\$0	\$0	\$0
Bldg. 19 - Storm Drain Outfall Alarm	\$5,000	\$0	\$0	\$0	\$0	\$0	\$0
Misc. Safety/Environmental Issues	\$100,000	\$100,000	\$100,000	\$100,000	\$100,000	\$100,000	\$100,000
Bldg. 40 - Chem Stores Facility Upgrade	\$25,000	\$50,000	\$50,000	\$60	\$0	\$0	\$0
Bldg. 20 - Cathodic Protection for Gas Tank	\$0	\$0	\$0	\$0	\$0	\$10,000	\$0
ire Alarm System - Plant-Wide	\$250,000	\$0	\$60	\$0	\$0	\$0	\$0
Plant Automation Management (PAM) Sys.	\$150,000	\$0	\$0	\$0	\$0	\$0	\$0
sphalt Repair - Salvage	\$70,000	\$0	\$0	\$0	\$0	\$0	\$0
sphalt Repair - Boiler House, Bldg. 36 & 37	\$0	\$0	\$100,000	\$0	\$0	\$0	\$0
sphalt Repair - General	\$0	\$0	\$0	\$0	\$50,000	\$0	\$0
sphalt Repair - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$800,000
ant-Wide Roof Replacement	\$0	\$0	\$0	\$0	\$100,000	\$100,000	\$0
dg. 72 - Installation of Scrubber	\$0	\$750,000	\$0	\$0	\$0	\$0	\$0
dg. 12 - Rinse Water Collection Sump	\$0	\$150,000	\$0	\$0	\$0	\$0	\$0
dg. 45 - Hazardous Waste Yard	\$0	\$50,000	\$0	\$0	\$0	\$0	\$0
ldgs 41 & 42 Boiler House Soil Cleanup	\$0	\$0	\$0	\$10,000	\$500,000	\$0	\$0
verhaul Industrial MT & Process Systems	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000	\$1,000,000
yde Ultrafilter - 24 Composite Sampler	\$3,000	\$0	\$0	\$0	\$0	\$0	<del> </del>
ooling Tower Replacement	\$140,000						1
Vaste Minimization (Centrifuge)	\$40,000						
uilding 34 Ventilation System	\$15,000						
ldg. 19 Emergency Diesel Generator	\$80,000					<u> </u>	<del>                                     </del>
uto Rinsewater Level/Overflow Controls	\$100,000				<del> </del>		
nprove Production Flow	\$0	\$500,000	\$1,500,000	\$500,000	\$1,500,000	\$1,000,000	\$1,000,000
Annual Totals:	\$2,891,000						\$2,900,000
5 Year Total:		<u> </u>	1		16,746,000	, , , , , , ,	1- /- /
7 Year Total:			***************************************		, , , , , , , , , , , , , , , , , , , ,	<u> </u>	\$21,856,000


• COMMENTS:

Funding for this project to be obtained from Safety and Environmental Affairs at Long Beach.


1.183 1.183 1.185 2.184

# **SUPPORTING DOCUMENTS**


## C6 - TORRANCE, PLANT LAYOUT




## **BUILDING 1**



# **BUILDING 2 - PLAN 4**



# **BUILDING 3 - PLAN 1**



### **BUILDING 66**

